

Test Report

No. CANEC1909434211

Date: 30 May 2019

Page 1 of 4

WINDAY ELECTRONIC (DONG GUAN) CO.,LTD

LONG QUAN INDUSTRY XIN-JIU-WEI TERRITORY LIAO BU VILLAGE DONGGUAN CITY GUANGDONG
523000, CHINA

The following sample(s) was/were submitted and identified on behalf of the clients as : METALLIZEDFILM
CAPACITOR(BOX)

SGS Job No. : CP19-026394 - SZ
Model No. : MPX(X1,X2)
Client Ref. Info. : MPX/MEX(X1,X2),MPC.MEC,MEB,MCB(CBB61-S0/S3),MMC,MXJ,MIT,
MC4
Date of Sample Received : 22 May 2019
Testing Period : 22 May 2019 - 30 May 2019
Test Requested : Selected test(s) as requested by client.
Test Method : Please refer to next page(s).
Test Results : Please refer to next page(s).

Signed for and on behalf of
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Annie Ren

Annie Ren
Approved Signatory



Test Report

No. CANEC1909434211

Date: 30 May 2019

Page 2 of 4

Test Results :

Test Part Description :

Specimen No.	SGS Sample ID	Description
SN1	CAN19-094342.007	METALLIZEDFILM CAPACITOR(BOX)(mixed)

Remarks :

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected (< MDL)
- (4) "-" = Not Regulated

Halogen

Test Method : With reference to EN 14582:2016, analysis was performed by IC.


<u>Test Item(s)</u>	<u>Unit</u>	<u>MDL</u>	<u>007</u>
Fluorine (F)	mg/kg	50	ND
Chlorine (Cl)	mg/kg	50	333
Bromine (Br)	mg/kg	50	ND
Iodine (I)	mg/kg	50	ND

Remark: The sample(s) was/were analyzed on behalf of the applicant as mixing sample in one testing. The above result(s) was/were only given as the informality value and only for reference.




ATTACHMENTS

Halogen Testing Flow Chart



Sample photo:



SGS authenticate the photo on original report only

*** End of Report ***

